Part - 1

Performa For The Safety School Building (To be filled by the Head of School / Institute)

1.	Name of School	Shannick christian School
2.	Location	Hombran Load
3.	Plot Area	3 Acra affore
.4.	Plinth Area	61020 85 feat
5	Number of Storey	Duysle
6.	Year of Construction of building	1993-99
7.	Supervision of the qualified Engineer, The following details may be given:	
	a) Name of the Engineer	Ar Novinder Sayao and Co. Lind Somorebay 1 Str. No 97 Ros
	b) Address	throl Somosbar, Str. No 97 Roa
	 c) Set of Structure Drawing used in the construction if available 	Hr. Region Targni 15-H Sarabha Napar luchhar
	d) Name of the Architect	15- H. Sarabha Nagar luchhar
8.	Whether the building has been constructed for	
	a) School	(Yes/No)
	b) Residential purpose and converted for use as a school	(Yes/No)
9	Materials used for Roof;	
	a) R.C.C. slabs	c(Yes/No)
	b) R.S. Joists and Battens	(Yes/No)
	c) Wooden Joists and Battens	(Yes/No)
10.	Materials used for walls:	
	a) Mud Mortar	(Yes/No),
	b) Cement Mortar	(Yes/No)
	c) Plaster (i) Lime Mortar	(Yes/No)
	(ii) Cement Mortar	(Yes/No)
11.	Flooring:	
	a) Conglomerate	(Yes/No),
i singitar	b) Terrazzo	
	c) Brick Paying	(Yes/No)
12.	Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows	1 Encluded

Signature with stamp of The Head of the School / Institutecipal Shamrock Christian School Hambran Road, Ludhlana.

Part-H (To be filled by S.D.E. of P.W.D. B&R Department)

I have visited the above mentioned school on 06/6/29 and have visually inspected it form all angles of safety and I found it fit for normal use as school building.

In case any addition / alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

In case the building is affected by flood or if there is settlement of walls / foundations or caves of roof etc. immediately inspection of the undersigned be arranged to check the stability and safety of the building.

This building can be safety occupied for normal use up to up to which it can be used).

31325

(indicate year

Sub Divisional Engineer Construction Sub Division No.3,

Construction Sub Division No.3,
Sub Divisional Engineer

ਪਿੱਠ ਅੰਕਣ ਨੰਬਰ 53-54 ਮਿਤੀ 06-06-24

- ।) ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ Principal, Shamrock Christian Sr. Sec. School, P.O. Partap Singh Wala, Hambran Road, Ludhiana ਨੂੰ ਸੂਚਨਾਂ ਅਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।
- 2) ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ: । ਲੋ.ਨਿ.ਵਿ. ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ ਨੂੰ ਸੂਚਨਾਂ ਅਤੇ ਅਗਲੇਰੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਨੰ: 3, ਲੋ,ਨਿ.ਵਿ.। ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਲੁਧਿਆਣਾ।